



Testing Laboratories, Inc.

940 South Harney St., Seattle, WA 98108 (206) 767-5060 FAX 767-5063

Chemistry, Microbiology, and Technical Services

CLIENT: Alaskan Copper Works
628 S. Hanford
Seattle, WA 98134
ATTN: Gerald Thompson

LABORATORY NO. 9204619

DATE: Jul. 23, 1992

PO# M23988

REPORT ON: ETHYLENE GLYCOL/FILTERS (SAMPLE & CONTROL)

SAMPLE

IDENTIFICATION: Submitted 04/09/92

TESTS PERFORMED
AND RESULTS:

ANALYSIS ETHYLENE GLYCOL


Specific Gravity, 25°C 1.113

ANALYSIS ON FILTERS

Both control and sample filter were ashed at 600°C so as to acquire possible residue for analysis. Residue upon ignition were insignificant on each sample and further analysis could not be performed.

Respectfully submitted,

LAUCKS TESTING LABORATORIES, INC.


Mark Babich

MB:bv



This report is submitted for the exclusive use of the person, partnership, or corporation to whom it is addressed. Subsequent use of the name of this company or any member of its staff in connection with the advertising or sale of any product or process will be granted only on contract. This company accepts no responsibility except for the due performance of inspection and/or analysis in good faith and according to the rules of the trade and of science.

Printed on Recycled Paper 

AKC-0014132

Laucks⁸²_{YUUS}

Testing Laboratories, Inc.

940 South Harney St., Seattle, Washington 98108 (206) 767-5060 FAX 767-5063

Invoice

Chemistry, Microbiology, and Technical Services

CLIENT: Alaskan Copper Works
628 S. Hanford
Seattle, WA 98134
ATTN: Gerald Thompson

INVOICE NO. 23783

DATE: Jul. 23, 1992

PO# M23988

LTL# 9204619

For the analysis of ETHYLENE GLYCOL ----- \$100.00

Net 30 Days

The sole liability of these laboratories for these services, including claims for negligence, strict liability in tort or warranty, shall not exceed the amount of this invoice. Samples may be discarded after analysis unless otherwise requested.

Fed. Empl. ID No. 91-0580763



AKC-0014133